

#### Work Permit # <u>DRL-2012-017 /SS-2012-</u>209 Work Order #

Job# Activity#

See "Instructions for Filling out the Work Permit" contained in the Work Planning and Control for Experiments and Operations Subject Area. 1. Work request WCC fills out this section. ☐ Standing Work Permit Dept/Div/Group: PO/PHENIX Requester: Don Lynch Date: 7/10/12012 Ext.: 2253 Other Contact person (if different from requester): Carter Biggs Ext.: 7515 Work Control Coordinator: Don Lynch Start Date: 7/16/2012 Est. End Date: 10/15/2012 Brief Description of Work: Enter MMN, Erect work platforms, repair/upgrade MuTr & MuTrgr Sta 2 & 3 Electronics Building: 1008 Room: IR Equipment: MuTr, MuTrgr, MMN | Service Provider MuTr/MuTrgr Experts, PHENIX Techs 2. WCC, Requester/Designee, Service Provider, and ESS&H (as necessary) fill out this section or attach analysis **ESS&H ANALYSIS Radiation Concerns**  None ☐ Activation Airborne Contamination Radiation □ NORM Other ☐ Special nuclear materials involved, notify Isotope Special Materials Group ☐ Fissionable/Radiological materials involved, notify Laboratory Nuclear Safety Officer Radiation Generating Devices: Radiography ☐ Moisture Density Gauges ☐ Soil Density Gauges X-ray Equipment Safety and Security Concerns ☐ Explosives ☐ Transport of Haz/Rad Material ☐ Pressurized Systems ☐ None ☐ Adding/Removing Walls or Roofs Critical Lift ☐ Fumes/Mist/Dust\* ☐ Railroad Work ☐ Asbestos ☐ Cryogenic ☐ Heat/Cold Stress ☐ Nanomaterials/particles\* Rigging ☐ Beryllium\* Electrical ☐ Hydraulic ☐ Noise\* ☐ Silica\* ☐ Lasers\* ☐ Non-ionizing Radiation\* ☐ Biohazard\* ☐ Security Concerns ☐ Chemicals/Corrosives\* Excavation Lead\* Oxygen Deficiency\* ☐ Suspect/Counterfeit Items Material Handling Confined Space\* ☐ Penetrating Fire Walls ☐ Vacuum Ergonomics\* \* Safety Health Rep. Review Required Haz. Rad. Bio Material Exceed DOE 151.1-C Levels - Contact OEM ☐ Other None None ☐ Work impacts Environmental Permit No. **Environmental Concerns** ☐ Land Use Institutional ☐ Atmospheric Discharges (rad/non-rad) ☐ Soil Activation/contamination ☐ Waste-Mixed Controls ☐ Chemical or Rad Material Storage or Use ☐ Liquid Discharges ☐ Waste-Clean ☐ Waste-Radioactive Cesspools (UIC) ☐ Oil/PCB Management ☐ Waste-Hazardous ☐ Waste-Regulated Medical ☐ High water/power consumption ☐ Waste-Industrial ☐ Spill potential ☐ Underground Duct/Piping Waste disposition by: ☐ Other Pollution Prevention (P2)/Waste Minimization Opportunity: ⊠ No □ Yes **FACILITY CONCERNS** ☐ Intermittent Energy Release None ☐ Potential to Cause a False Alarm ☐ Vibrations ☐ Electrical Noise ☐ Access/Egress Limitations □ Temperature Change Other ☐ Impacts Facility Use Agreement Configuration Management Maintenance Work on Ventilation Systems Utility Interruptions **WORK CONTROLS Work Practices** ☐ Exhaust Ventilation □ Spill Containment ■ None ☐ Security (see Instruction Sheet) □ Back-up Person/Watch ☐ HP Coverage ☐ Posting/Warning Signs ☐ Time Limitation ☐ Other ☐ Electrical Inspection Required ☐ Barricades ☐ IH Survey ☐ Warning Alarm (i.e. "high level") Personal Protective Equipment ☐ None ☐ Ear Plugs ⊠ Gloves as appropriate
 ☐ Lab Coat ☐ Coveralls ☐ Ear Muffs ☐ Respirator\* ☐ Goggles ☐ Safety Harness ☐ Disposable Clothing ☐ Face Shield ☐ Hard Hat ☐ Shoe Covers ☐ High visibility cloths/vest ☐ Other Permits Required (Permits must be valid when job is scheduled.) None ☐ Cutting/Welding ☐ Impair Fire Protection Systems □ Digging/Core ☐ Concrete/Masonry Penetration Rad Work Permit-RWP No Drilling ☐ Electrical Working ☐ Confined Space Entry Other Confined Space 2A certification Dosimetry/Monitoring Real Time Monitor ■ None ☐ Heat Stress Monitor □ TLD ☐ Noise Survey/Dosimeter ☐ Self-reading Pencil Dosimeter ☐ Waste Characterization ☐ Air Effluent O<sub>2</sub>/Combustible Gas ☐ Ground Water Self-reading Digital Dosimeter Other Check O2 level prior to entry ☐ Liquid Effluent Passive Vapor Monitor ☐ Sorbent Tube/Filter Pump Training Requirements (List specific training requirements) Confined Space, CA-Colider User, PHENIX Awareness, scaffold training, ladder training, working at heights Based on analysis above, the Review Team determines the risk, complexity, and If using the permit when all hazard ratings are low, only the following need to sign: ( coordination ratings below: Although allowed, there is no need to use back of form) ESS&H Risk Level: Low ☐ High WCC: Date: Complexity Level: ∠ Low ☐ High Service Provider: Work Coordination: ☐ Low ☐ High Authorization to start Date: (Department/Division, or their equivalent, Sup/WCC/Designee)

Work Plan (procedures, timing, equipment, scheduling, coordination, notifications, and personnel availability need to be addressed in adequate detail): See attached work plan and procedure				
Special Working Conditions Required	(e.a. Industrial Hygiene hold point	s or other monitoring)		
	(c.g., madothal rrygione noid point	o or other monitoring)		
None  Notifications to operations and Operati	ional Limits Requirements: None			
Post Work Testing, Notification or Doc	· · · · · · · · · · · · · · · · · · ·			
Job Safety Analysis Required: ☐ Ye	<u> </u>	Review Done: X in serie	es □ team	
oob callety / maryone recognition.	,	TOTOM BOILD.	50 <u> </u>	
that could impact ESS&H have been of	considered and controls established	m members were appropriate for the work that vid according to BNL requirements. In addition, this have been identified and recorded on this permitted and recorded on this permitted.	nis signature indicates that applica	
<u>Title</u>	Name (print)	<u>Signature</u>	Life #	Date
ES&H Professional				
F&O Facility Project Manager				
Service Provider				
Work Control Coordinator	Don Lynch		20146	
Safety Health Representative				
Research Space Manager				
Other				
Other (PHENIX Escort)				
Required Walkdown Completed				
*Primary Reviewer				
	erforming work have read and unc	esection. erstand the hazards and permit requirements (in ures also includes verification that worker trainin Contractor Supervisor:		
Workers:	Life#:	Workers :	Life#:	
TTOTAGE.	Lion.	Trondro.	Enon.	
Workers are encouraged to provide fee	edback on ESS&H concerns or on	ideas for improved job work flow. Use feedback	k form or space below.	
		, ,		
5. Department/Division, or thei	<u> </u>			
		rk controls are in place and site is ready for job.	,	
Name:	Signature:	Life#:	Date:	
6. Worker provides feedback.				
Worker Feedback (use attached she	ets as necessary)			
a) WCM/WCC: Are there an	y changes as a result of worker fe	edback? 🗌 Yes 🔲 No		
Note: See Work Planning and Control	for Experiments and Operations S	Subject Area section 2.6.		
7. Post Job Review/Closeout: Vacceptable condition. (WCC car	Nork Control Coordinator (an In delegate clean up of job sit	uthorizing dept.) checks quality of competo work supervisor.) The WCC ensure		
postings, procedures, etc., is initial Name:	Signature:	Life#:	Date:	
Comments:	Oignature.	LIIOTT.	Date.	

#### MMN Entry During Shutdown for MuTr/MuTrigger North Troubleshooting

#### **INTRODUCTION**

Muon Tracker Detector (MuTr) and MuTrigger experts need to access the interior of the North Muon Magnet to install/troubleshoot/test noise reduction mechanically attached capacitors to MuTr detector subsystem electronics during the 2012maintenance summer shutdown period after the end of run 11 of the PHENIX experiment and to perform additional troubleshooting and repairs on MuTr and MuTrigger front end electronics (FEE's). During this period purge gas conditions (inert gases) for subsystems in the MMN will be maintained.

#### MMN MuTr TTS&R (Troubleshoot, Test and Repair)

The following operations will take place the PHENIX 2012 maintenance shutdow periods.

- 1. For the duration shutdown during which the MMN will be entered as described herein, all PHENIX magnets will be ramped down and locked out.
- 2. Prior to the first maintenance period for which entry into the MMN is required, C-A safety shall be contacted to sample the internal atmosphere of the MMN. When C-A safety arrives to take the, the sliding access panel shall be opened to permit sampling and an O<sub>2</sub> content check of the MMN internal atmosphere shall be sampled and recorded on a copy of the attached sheet. Each monitoring check shall have its own record sheet.
- 3. The C-A confined space safety expert shall determine from the tests whether it is safe to enter the MMN for the purposes stated herein. *In no event shall anyone enter the MMN prior to approval of the C-A confined space monitoring expert.*
- 4. During the entire maintenance period in which personnel may be inside the MMN, a 100 cfm blower shall direct external air into the MMN cavity.
- 5. After clearance to enter has been approved, properly trained PHENIX technicians and BNL carpenter(s) shall sign the entry log sheet (attached) and may then enter and construct elevated work platforms as described in PHENIX document DRL-ECD-2012-002 rev D, for the purpose of accessing MuTr and MuTrigger FEE's and detector electronics at elevated areas within the North Muon Magnet (MNN). At any time when any personnel are inside of the MMN an additional watch person shall be stationed outside of the MMN and adjacent to the hatch to monitor the well being of those engaged in work inside. The watch person shall have no other responsibilities during his watch and may not leave his post unless relieved by an equally qualified and dedicated watch person. All work platforms shall be reviewed, inspected and approved by appropriately qualified PHENIX engineering prior to permitting work to be performed on such platforms. At various times during the troubleshooting and repairs, adjustments and changes to the work platforms shall be made to better access different areas in the MMN. After each such adjustment, an appropriately qualified PHENIX engineer shall review, inspect and approve such platform prior to releasing it for use. All inspections shall be documented on the attached MMN work platform inspection sheet.

Note: at all times the number of persons and the combined weight of persons and equipment shall be below the maximum allowable (2 persons and less than 600 lbs on each platform, 3 persons and less than 900 lbs on all platforms in the MMN). This is in accordance with the design calculations of DRL-ECD-2012-002 rev D.


- 6. After clearance work platforms have been erected, properly trained MuTr subsystem and MuTrigger FEE experts and/or properly trained PHENIX technicians shall sign the entry log sheet (attached) and may then enter and perform troubleshooting and operational checks. At any time when any personnel are inside of the MMN an additional watch person shall be stationed outside of the MMN and adjacent to the hatch to monitor the well being of those engaged in work inside. The watch person shall have no other responsibilities during his watch and may not leave his post unless relieved by an equally qualified and dedicated watch person. All those inside the MMN and the watch person shall have current BNL confined safety training and shall comply with all requirements of the BNL Confined Space SBMS standards. As work progresses *This work permit*, the MMN entry log, platform inspection sheet(s) and the Confined Space Entry Certification Form shall be posted near the access hatch.
- 7. During testing, HV to the MuTr detector panels may turned on and off to trouble shoot faults and test quality of the repair/test connections. Current/voltage limits on MuTr components are within allowable working limits per the PHENIX Awareness Procedure and/or properly shielded from personnel contact and do not require any additional permits.
- 7. After all work has been completed and no additional access to the interior MMN is required for the current maintenance shutdown period all equipment brought into the MMN shall be removed, work platforms dismantled, the MMN access panel closed, and the MMN lockout removed.
- 8. After all tasks covered by this work permit have been completed, all equipment brought into the MMN has been removed, the MMN access panel closed and the MMN lockout removed, this work permit shall be closed and all relevant observations and comments concerning the work performed under this work permit shall be recorded. Should additional subsequent work in the MMN be required, a new work permit shall be generated.

# MuTr Station 2 & 3 Re-Capacitation and Termination

Re-capacitation of MuTr stations 2 and 3 (inside MMS and MMN magnets) will be done using clamping and installation technique developed by MuTr experts during run 12 as was performed during 2011 shutdown. Method requires no soldering or gluing, requiring only mechanical clamps.

During 2011 summer shutdown only areas requiring no interior scaffolding or elevated work platforms were addressed. Elevated work in MMN and MMS will be performed during 2012 shutdown.

# Station-3 Clamp Installation





- Anode card Inspection with mirror: < 5min/clamp.</li>
- Anode clean up if necessary: < 15 min./clamp</li>
- Clamp mount : ~ 5min./clamp
- Voltage readout : 5min./clamp
- HV test: 10min.
- Total: 25 ~ 40 min./clamp




# North Sta-2 Oct-2 HV Repairs

5/12 HV channels in North Sta-2 Oct-2 bad

- located on interior of magnet at top
- · pull dry air minifold
- investigate why these channels bad
- potentially remove and replace capacitors
- or isolate broken wires and disconnect from HV to recover other wires in same HV channel
- replace dry air manifold

Also check HV clampterminators in North Sta-3 (3 HV channels are disabled); and in South







## Clamp-on Terminator Installation on North & South Station-3


- Lower clamp-on terminators already installed for both north and south sta-3 (bottom 4 octants)
- with new work platforms that reaches all of sta-3; install remaining (upper) clamp-on terminators.
   Analyses submitted to CAD engineering.

















MMS Work Platforms


MMN Work Platforms

# South Station-2

Location of electronics to be serviced




No boards in station-3 need to be served.



# North Station-3

Octant-4
MuTrig Electronics
boards need to be
replaced by spare

No boards in station-2 need to be served.



### 2012 Shutdown Schedule

Prep for shutdown  Define tasks and goals  Analysis and design of fixtures, tools and procedures Fabricate/procure tools and fixtures Tests, mockups, prototypes Receive, fabricate, modify, finish installables Review and approval of parts, tools, fixtures and procedures Assembly and QA tests AH Crane Upgrade (variable speed & wireless remote)	2/1-6/25/2011
End of Run Party Run 12 Ends Shutdown Standard Tasks • Open wall, disassemble wall, Remove MuID Collars, • Move EC to AH, etc.	6/22/2012 6/25/2012 6/25-7/20/2012
VTX Strip-pixel post run tests FVTX post run tests Disassemble VTX/FVTX services July 4th Holiday	6/25-6/30/2012 7/1-7/8/2012 7/9-7/27/2012 7/4/2012
Open Station 1 North, remove MPC North for repairs RPC1 North Cooling Upgrade Temporary power patch for IR and AH lights and cranes AH electrical power panel upgrades	7/9-13/2012 7/9-13/2012 7/16-7/20 7/16-9/15
Remove VTX/FVTX and transport to Chemistry Lab Remove MMS & MMN vertical East lampshades Summer Sunday (8/5) Prep and teardown Summer Sunday (RHIC)	7/30/2012 7/23-7/27/2012 8/1-8/7/2012 8/5/12

## 2012 Shutdown Schedule (Continued)

MuTr South Station 1 work	
Install access (Sta. 1work platforms)	7/30-8/3/2012
Disconnect Cables, hoses etc, ID/label all	8/6-8/10/2012
Remove FEE plates and chambers	8/13-8/17/2012
Station 2 Terminators and manifold upgrade through	8/20/-8/31/2012
access opened by station 1 removal	
MPC South repairs	8/20-9/15/2012
RPC 1 South cooling upgrade	8/20-9/15/2012
Labor Day Holiday	9/3/2012
MuTr South Station 1 work (Cont'd)	
Clean/install new MuTr Sta. 1 chamber parts and upgrades	8/20/-9/7/2012
(concurrent At RPC Factory)	
Re-install chambers and FEE plates	9/10-9/14/2012
Re-cable, re-hose and test	9/10-9/28/2012
re-capacitation and air manifold upgrades	
Station 3 North and South (upper half)	7/23-9/30/2012
Repair upgrade, reassemble VTX/FVTX	7/23-10/5/2012
Test, survey (at Chemistry and IR) and re-install VTX/FVTX	10/8-11/9/2012
Substation breaker upgrade/test (CAD)	8/20-9/30
AH utility power distribution upgrade	8/20-9/30
DC West maintenance (replace window)	9/15-10/15
RPC stations 1 and 3, north and south maintenance	As required
Other detector maintenance as required	As required
Infrastructure maintenance as required	As required
TBD prototype tasks	As required
Open Station 1 North, re-install MPC North	10/16-10/26/2012
RPC1 North Cooling upgrade (if not completed earlier)	10/16-10/26/2012

PHENIX 2012 Shutdown

#### 2012 Shutdown Schedule (Continued)

Veterans Day Holiday
Pre-run commissioning and prep for run 13
Prep for EC roll in
Roll in EC
Thanksgiving Holidays
Prep IR for run
Pink/Blue/White sheets
Christmas Holidays
Start run 13

11/12/201212 11/1-12/31/2012 11/12-11/16/2012 11/19-11/21/2012 11/22-23/2012 11/26-12/3/2010 12/3-12/21/201 12/24-25/2012 1/1/2013



#### CONFINED SPACE ENTRY CERTIFICATION

Location	N. 4 (100)		Date	
Building 1008, IR, Muon Magnet		•		
Department PO	Divi			
Building	PHENIX Area/Location/Room:			
1008	IR, N			
Supervisor/Designee	III, I	IIVIII	Life #	
Don Lynch/J. Carter Biggs 20146/15639			39	
	PRE-ENTRY QUEST	ONS		
For each item, check "yes" or "no":			YES	NO
Is entry essential to perform work?	?			
Have all personnel been trained in	confined space entry?			
Are conditions safe to remove utili	ity-hole cover?			
Has opening been guarded?				
Is monitoring equipment calibrated	d?			
Has monitoring been performed ar	nd recorded below?			
Is GFCI used, if outside or in wet	conditions?			
Is ventilation blown into bottom of	f space? (If required)			
Are personnel instructed to evacua	te upon hazard detection?			
Have all workers reviewed these e	ntry requirements?			
Radiation: If present, RWP may be	e required – review work with ESH Coo	ordinator and RCD	Reviewed	
personnel. Evaluate hazards and c	controls.			
	SPACE CLASSIFICATION	QUESTIONS		
	em, check box only if "yes"	Class 2A	Class 2B	Class 2C
Engulfment Hazard Present				
Entrapment Hazard Present				
Electrical Systems:				
<ul> <li>Deenergized</li> </ul>		X		
<ul> <li>Energized and Working Hot</li> </ul>				
• Energized, but Guarded or not	t Working Hot			
Mechanical Systems:		n/a		
• Deenergized				
<ul> <li>Energized and Working Hot</li> </ul>				
<ul> <li>Energized but Guarded or not</li> </ul>				
Other Energized Systems: (e.g., ste	eam, sewage)	n/a		
• Deenergized				
Energized and Working Hot				
<ul> <li>Energized but Guarded or not</li> </ul>				
	ce, based upon monitoring, but controlla	able by X		
Ventilating - Monitor for O <sub>2</sub> prior		11 1 1 1		
	ce, based upon monitoring, but not cont	rollable by n/a		
ventilating Chamical Sources introduced into	space? (e.g., welding fumes, solvents)	n/a		
High Temperature/Pressure Hazard		n/a		
	checked, a Confined Space Permit <b>IS</b> re			
	ecked, and none in column 2C, a Confi	-	equired RUT co	ntinuous
<ul> <li>If any box in column 2B is che monitoring and ventilating AF</li> </ul>		nea space i cillit 13 NOT I	equired <b>DU I</b> CO	minuous
	e checked, no additional requirements:	nnly		
- 11 only boxes in column 2A di	Classification eva			
CLASSIFICATION	Ciacomication eva			
	I have completed the front and back of the			
class:2A	space. If the confined space is classified			
	is Class 2B, continuous monitoring and v	entilation is required and will b	be documented on	this form.
	Supervisor/Designee:	Life#	Date:	

1.0/3s02e011.doc 1 (06/2003)

#### **BNL CONFINED SPACE ENTRY CERTIFICATION**

Meter:	Serial #	Calibration Date:
Day of Use Sensor Check □ Yes □ No		
Tested By:		BNL#:

MONITORING RESULTS					
Tested By:		BNL Number:			
Date/ Time	Oxygen % (% O2)	Flammable Gas (% LEL)	Carbon Monoxide (CO ppm)	Hydrogen Sulfide (H2S ppm)	Other:
Pre-Entry Certification test					
Acceptable Reading	19.5 – 23.5 %	< 10 % of LEL	<25 ppm	<10 ppm	

Supplemental sampling record

#### **CLASS 2B CONFINED SPACE ENTRY CERTIFICATION**

For Class2B spaces, continuous monitoring is required.

#### MONITORING RESULTS Tested By: BNL Number: Hydrogen Sulfide Oxygen % Flammable Gas Carbon Monoxide Other: Date/ Time (% O2) (% LEL) (CO ppm) (H2S ppm) Acceptable Reading 19.5 – 23.5 % < 10 % of LEL 25 ppm 10 ppm

Class 2B: Describe Method of Ventilation:		

#### **Muon Magnet Confined Space Entry Certification Sheet**

The undersigned certify that they have taken the BNL Confined Space Training, BNL Course # **HP-OSH-016**, within the last twenty four months, and understand the hazards involved in working in the south and north muon magnets (**MMS and MMN**).

DATE	SIGNATURE	LIFE/GUEST #

# Brookhaven National Laboratory PHENIX MMN, MMS and Station 1 Scaffolds

#### **Scaffold Safety Checklist**

	<u> </u>		
Project & Scaffold:	Job#	WO #:	
Date of Inspection:	Competent Person(s):		
Date Scaffold is complete:			

	YES	NO	COMMENTS
1. Have all personnel been trained in the safe use of the			
scaffold being used?			
2. Is a 'Competent Person' in charge of scaffold erection,			
dismantling, moving, or alteration?			
3. Have hazardous conditions been identified and guarded			
against, such as:			
Electric power lines?			
Be Beampipe protected?			
MuTr chambers covered?			
Magnets locked out?			
4. Is the scaffold erected in accordance with design			
drawings?			
5. Are scaffold components and planking in safe condition			
for use and is plank graded for scaffold use?			
6. Are base plates and/or screw jacks in firm and stable			
contact with the base surface?  7. Is scaffold level and plumb?			
8. Are all scaffold legs braced and are all braces properly			
attached?			
9. Is the scaffold platform free of makeshift devices or			
ladders to increase the working height of the scaffold?			
10. Are guardrails installed properly, including toeboards?			
11. Are guardrails in place on all open sides and ends of			
scaffold platforms above 6' in height?			
12. Have all joints been secured with set screw and torqued			
to mfr. tolerances (screw heads to be marked to verify.			
13. Has scaffold been secured to building or structure at			
least every 30' in length and 26' in height?			
14. Have free standing towers been guyed or tied every 26'			
in height?			
15. Has scaffold been inspected and approved by C-A			
designated inspector(s)?			
16. Use space below and back of page for additional			
comments.			